Must ship July 300 Spirt

Work Order ID 60774-	2	2
----------------------	---	---

Thursday, July 22, 2010 12:58:35 PM

	IIII	IIII	IIII	III	
				Ш	Ш

Page 1

Thursday, July 22, 2010 12:38.33 FW		Accept			IIIII	Setup	Start		
Revision ID: PRELIM Crosstube Lug Assembly, Fwd Start Date: 7/22/2010 Start Qty: 4.00 Required Date: 7/29/2010 Req'd Qty: 4.00 Reference:	(1980) 9191 1891	To be a second	Cust Item I Customer:				Stop		
Approvals: Process Plan:	Date: /0-7-23	Tooling: SPC (Y/N):		ite:		Run	Start Stop		
Sequence ID/ Operation Work Center ID Description		Set Up/ Run Hours	Tool ID	Tool # Plan Code	Accep Qty	ot Rej Qty		Reject Number	Insp. Stamp
Draw Nbr Revision Nbr									
D4148 PAT B \$ (0.0)	1,22								
Small Fab Memo	nble as per dwg	0.00			5/	50/	67	127	0
QC5- Inspect part co	empleteness to step on W/O	0.00	2/2/27		_6	2			
120 Identify as per dwg a light ligh	& Stock Location: 468	0.00		•	_/	0/7	hz	4	9/

Work Order ID 60774 Stop Thursday, July 22, 2010 12:58:35 PM Accept D4148-041 Item ID: Cust Item ID: PRELIM Crosstube Lug Assembly, Fwd Revision ID: Customer: Item Name: Start Qty: 4.00 Start Run 7/22/2010 Req'd Qty: 4.00 Start Date: Stop Required Date: 7/29/2010 Date: Tooling: Insp. Date: Reject Reference: Reject Date: Stamp Accept SPC (Y/N): Number Process Plan: Tool# Plan Qty Tool ID Date: Qty Approvals: Code Set Up/ QC: Run Hours Operation 0.00 Sequence ID/ Description QC21- Final Inspection - Work Order Release Work Center ID 0.00 Memo Quality Control L (De 07 28


## **Picklist Print**

Thursday, July 22, 2010 12:58:39 PM

Work Order ID: 60774

Parent Item: D4148-041

Parent Item Name: Crosstube Lug Assembly, Fwd



Start Date: 7/22/2010 Start Qty: 4.00 Required Date: 7/29/2010

Required Qty: 4.00

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch		Primary Location	Last Locatio	Route on Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date S Issued	Status
D2690-6  Lanyard Assembly	III	Manufactured	No			100	Each	24.0000	1	350	0/07	127	
				Location	L,	Lo	e Qty	Loc Code					
				ST020			24		_	8	-17-61		
D3908-5/ _ 1//	1	NA	Me		59960	192	24		140	#1			
	Ш	Manufactured	No			100	Each	15,0000	1	4			
Lyeboly Stud	07.22										2		
10.0	)			Location		T <sub>a</sub>	c Qty						
				GA		1.0	COLV	Loc Code		k H			
		114			57428		1		_				
		10.15		ST095			14		-		- 44		
,		110			58850		4			N I			
D4148-1		Manufactured	No		59670	100	10				- I III		
	Ш	Manufactured	140		B	100	Each	0.0000	2	8	0/	11	/
Crosstube Lug Plate, Fwd					1.5	60777	Hall I			8) 2	100	107/0	22
D4148-3		Manufactured	No			100	Each	0.0000	1	1			
	III		4	· ·				0.0000	IIIIIWi /	41	66		1
Stud Receiver, Lower	•	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1				B 6077	2			4)6	19)	2/07/	2
-D3910-I		Manufactured	No			100	Each	24.0000	ī	1			
		117								1	2 6	12.	7
Crosstube Lug									9	50/0	107	100 +	4
				Location		Loc	Oty	Loc Code		1			
101		H.I.		st507			24		_				
22.0					59349 59708		23		_	91		Alet 1	
14148-5	gty 1	Batch: G	000	21	39708		1		- F	-			

## **Picklist Print**

Thursday, July 22, 2010 12:58:39 PM

Work Order ID: 60774

Parent Item:

D4148-041

Parent Item Name: Crosstube Lug Assembly, Fwd



Start Date: 7/22/2010

Start Qty: 4.00

Required Date: 7/29/2010

Page 2

Required Qty: 4.00

D4091-1

Mounting Lug

Manufactured

Purchased

No

No

100

100

Each

2.0000

AN3CI2A

Bolts

Location ST460

60239

100 Each

Loc Qty

Loc Qty

104

50

50

Loc Qty

Loc Code

44.0000

Loc Code

VAN4CI3A

BOLT

Purchased

ST351

Location

ST357

Location

112314 114761 115016

113359 114108 114442

114615

22 14 Each

104.0000

Loc Code

Thursday, July 22, 2010 12:58:39 PM

Shop Packet Print

Page 2

## Picklist Print

Thursday, July 22, 2010 12:58:39 PM

Work Order ID: 60774

Parent Item:

D4148-041

Parent Item Name: Crosstube Lug Assembly, Fwd

MS17984-C413

Purchased

No

No

No

Location

114808

115054

ST323



PIN, QUICK RELEASE

VMS20615-4M20 18

Purchased

RIVET

V<sub>MS21043-3</sub>

Purchased

Nut



Start Date: 7/22/2010

Start Qty: 4.00

Required Date: 7/29/2010

Required Qty: 4.00

100 Each 28.0000

Loc Oty

100

322

152

170

Each

Location Loc Qty ST297 114340 ST314 24 114523 114774 114886 20 100

Loc Code Each 322,0000

Loc Code

2,981.000

Location Loc Oty FG 76 103691 76 ST301 2905 112314 2905

Loc Code

## **Picklist Print** Thursday, July 22, 2010 12:58:39 PM


Page 4

Work Order ID: 60774

Parent Item:

D4148-041

Parent Item Name: Crosstube Lug Assembly, Fwd



Start Date: 7/22/2010 Start Qty: 4.00

Required Date: 7/29/2010

Required Qty: 4.00



Purchased

No

No

No

100 Each 1,220.000

Loc Code

8

Locatio	n	Lo	c Oty
FG			40
	104603		40
ST301			1180
	112492		25
	113069		8
	114348		347
	114523		500
	114784		300
		100	Ea

115000

3,480.000



NAS1149C0332R Purchased

Washer

Location Loc Oty Loc Code ST297 3480 113524 10 113737 150

100

3320 Each 730.0000

Each



NAS1149C0432R Purchased

> Location Loc Qty ST297 114292 140 114742 590

Loc Code

